

# FUGRO TECHNICAL SERVICES LIMITED

Fugro Development Centre,  
5 Lok Yi Street, Tai Lam,  
Tuen Mun, N.T.,  
Hong Kong.

Tel : +852 2450 8233  
Fax : +852 2450 6138  
E-mail : matlab@fugro.com.hk  
Website : www.materiallab.com.hk

# MaterialLab

Report No. : 151425EN150650(1)A



Page 1 of 1

## Test Report on Analysis of Mirror

### Information Supplied by Client

Client : DSA Company Limited  
Client's address : Room 03, 19/F, New Commerce Centre,  
19 On Sun Street, Shatin NT, HK  
Project : -  
Sample description : One sample of 6mm Thick Mirror  
Sample identification : -  
Test required : Neutral Salt Spray Test for 24 hours

### Laboratory Information

Lab sample I.D. : EN150650/1  
Date of receipt of sample : 03/06/2015  
Date test completed : 26/06/2015  
Test method used : BS EN ISO 9227 : 2012

### Results :

Lab Sample ID	Result
EN150650/1	No discernible change

Note: Photos of test specimen before and after neutral salt spray test are attached in Appendix.

Remark : This report is to supersede our former report #151425EN150650(1).

Supervised by :           K.F. Wong          

Certified by :   
Approved Signatory : HO Kin Man, John  
Manager – Chemistry Department



Date :           28/10/2015            
\*\* End of Report \*\*

Note : This report refers only to the sample(s) tested.

# FUGRO TECHNICAL SERVICES LIMITED


Fugro Development Centre,  
5 Lok Yi Street, Tai Lam,  
Tuen Mun, N.T.,  
Hong Kong.

Tel : +852 2450 8233  
Fax : +852 2450 6138  
E-mail : matlab@fugro.com.hk  
Website : www.materialab.com.hk


# Materialab

Report No. : 151425EN150650(1)A

## Appendix



Photos of test specimen before neutral salt spray test.



Photos of test specimen after neutral salt spray test for 24 hours.



*Note : This report refers only to the sample(s) tested.*